


Detector Cabinet For OGA systems

34847	Power Puls 3A 72W, replacement for earlier powers
34831	Power Puls 4,2A 100W, replacement for earlier powers
12080	HC sensor for OGA system
12081	HC sensor for OGA in cabinet
12082	O2 sensor for OGA
12083	H2S sensor for OGA
12084	Flow sensor 0-60/h for OGA
12085	Omicron Propane sensor complete for OGA
12088	Omicron SO2 sensor for OGA
12089	Flow sensor 0-360/h for OGA
51521	Flow sensor cell 0-60 L/H for OGA
55098	Hoseclip for OGA sensors
94120	1/4" Inch male union
96200	O2 sensor KE-50 for OGA
96210	Hc sensor/P300 for OGA
96211	H2S sensor/7HH-LM for OGA
36010	Sample pump 115/230VAC N3
36013	Sample Pump 115/230VAC N5
36012	Rep Kit for vacuum pump N5/N3



Various sensors in the APEX family

76105	APEX HC sensor 0-100%L.E.L. complete, 2110N2280
75750	APEX H2S sensor 0-50 P.P.M. complete
75749	APEX Transmitter ATEX Certified 2 x M25, 2110B2200
75718	APEX Transmitter unit fixture kit, 2110B2827
75721	APEX Transmitter unit Interconnect PCB, 2110B1822
75722	APEX Transmitter unit LCD module 2110B2820
75723	APEX Transmitter unit lid O-ring, 2110B2829
75724	APEX Transmitter unit Main board assembly, 2110B2821
75725	APEX Transmitter Ribbon cable, 2110B2833
75720	APEX Certified sensor, 2110B2070
75715	APEX Plug-In Cartridge O2 21%, 2110B3380
75748	APEX Plug-In Cartridge Methane 0-100%LEL, 2110B3704
75752	APEX Plug-In Cartridge H2S 0-50ppm, 2110B3240
75766	APEX Plug-In Cartridge N-butan 0-100%LEL, 2110B3752
75734	APEX Plug-In Cartridge CO, 0-500ppm, 2110B3160
75727	APEX Oxygen Transducer adapter, 2110B2802
75717	APEX Black cage for cartridge
75719	APEX Carbon filter, 2110B2172
75728	APEX Mesh filter, 2110B2170
75729	APEX Hydrophobic filter, 2110B2171
75747	APEX Duct mounting kit SS316L, 90053-A-7001
75716	APEX Test cap for Duct mounting kit
75726	APEX Sunshade, 2110B2152
75756	APEX OPUS/APEX weather protection, 2110B2150
75767	APEX Flowhousing for OPUS and APEX, 2110B2140

Transmitter-->

Sensor-->

Cartridge-->

Lock ring-->



Various sensors in the OPTIMA family

- 76100 Optima Plus IR Optima Pluss 0-100% L.E.L., 2108N5000
- 76103 Optima Plus W/Hawke (PL612) connection box
- 76104 Optima Plus IR Optima Pluss w/flowcap
- 76107 Optima Plus 0-100% LEL / weather protection
- 75708 Optima Plus 0-100%Vol Methane
- 76102 Optima Plus IR sensor duct mounting
- 75709 Optima Plus Plastic Nuts for flow housing
- 75710 Optima Plus Dust cover/barrier
- 75711 Optima Plus Sunshade/deluge protection
- 75754 Optima Plus Remote gassing cell
- 75788 Optima Plus, Flowhousing, 2108D0282
- 75789 Optima Plus, Optima Plus Gassing cover, 2108D0258
- 75790 Optima Plus, Weather protection, 2108D0276
- 75799 Optima Plus, Optima Plus Duct mounting kit, 04200-A-1015
- 75775 Optima Plus, Calibration Unit for Optima IR, Interigator

" Be aware that if you have the old type OPTIMA, that you mention this in the event of an enquiry so that you get the correct parts supplied. Easiest way to check this is to take a look at the sticker on your OPTIMA, if this is red you have the older version. If this sticker is not visible, turn the metal strap (*) on the sensor until you can read which sensor you need parts for. "

* Please see below picture, the sticker is at the "end" of the sensor and the metal strap is almost in the centre of the sensor.



Temperature Sensors (PT 100)

95245	Temperature sensor W-GYK.
95246	Temperature sensor W-SOK.
95247	PT 100 Housing MH-M-6.0-3-1, specify length
96178	Transmitter Ex PT100, 4-20 mA (PR5333)

